



Calibration Guidance for Touch Screen

1. Open the touch software,  select the "Tools" option in the pop-up window, and then select the "4 Points Calibration" option, As shown in the following pic:



2. Then it goes into calibration mode. In the calibration mode, touch the center of circle which appears in the lower left corner, the upper right corner, and the upper left corner, until the word "OK" appears. Details please refer to the following pic:



Tips: In case of non-function of touch caused by re-installing the operation system or the touch driver is unloaded or for any other reason, please follow the Touch Driver Installation Guidance to install the touch driver.